

RECALL No. 22T-020

## IMPORTANT SAFETY RECALL NOTICE

**This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.**

Dear Owner of an Alliance or Primex brand tire meeting the description listed below.

Yokohama Off-Highway Tires America, Inc. has determined that a noncompliance with Federal Motor Vehicle Safety Standard (VMVSS) No. 119 exists which relates to the date code included as the last four digits of the Tire Identification Number on certain Alliance and Primex tires as described below.

**IMPORTANT!!**

- Your Tire is being recalled
- You should contact your nearest Yokohama Off-Highway Tires America, Inc. (YOHTA) tire dealer to schedule an inspection of your tires

Description of Tires Subject to Recall

Subject tires must have all Five Characteristics Marked on the Sidewall

|-----Five Characteristics-----|

Brand	Size	Model Name	Load Range	Manufacturing Date Code(s)	Product No.
Alliance	12.5L-15FI	High Speed Rib	Load Range F	5219	54300104
Alliance	11L-15 FI	High Speed Rib	Load Range F	0820 or 2020	54300010
Primex	11-22.5	Highway R-550	Load Range G	0120, 0520 or 2020	407366-33
Alliance	11L-15 FI	Stubble Proof 319 SPH	Load Range F	2020	31900030
Alliance	10.5-20 IMP	317	12PR	2021	31706505

Yokohama Off-Highway Tires America, Inc.  
 201 Edgewater Drive, Suite 285  
 Wakefield, MA 01880  
 Ph: 339-900-8080  
[www.yokohama-oh.com](http://www.yokohama-oh.com)

### IDENTIFYING TIRES SUBJECT TO RECALL

For your assistance in identifying the tires that are subject to this campaign, we have attached a tire sidewall drawing for each of the subject tires in the chart above. Each sidewall drawing shows the Five Characteristics: i) brand name ii) tire size, iii) model name, iv) load range and v) manufacturing date code. In order for a tire to be subject to replacement under this program, the tire must have sidewall markings that match all Five Characteristics of one of the tires in the chart above.

### REASON FOR THIS RECALL

These tires, manufactured by a YOHTA affiliate India and meeting the descriptions listed above, may not be compliant with FMVSS No. 119. The incorrect date code tire may have been included in the Tire Identification Number on the sidewall of the tire.

The incorrect date code hinders drivers from accurately identifying the age of the tire and makes it difficult to determine if the tire is affected by a safety recall, which can increase the risk of a crash.

### WHAT YOKOHAMA OFF-HIGHWAY TIRES AMERICA, INC. (YOHTA) WILL DO

YOHTA will arrange for replacement of any tires subject to this recall with tires of equivalent value, free of charge. This replacement includes the cost of mounting and balancing the replacement tires.

### WHAT YOU SHOULD DO

Please contact an authorized YOHTA tire dealer as soon as possible to schedule a service appointment at the dealership for replacement of the subject tire. Instructions for replacing this tire have been sent to your dealer. You will have 180 days from the date you receive this letter to take advantage of the free replacement policy. The time necessary to perform this service correction is approximately 30 minutes per tire. Your authorized YOHTA tire dealer is best equipped to obtain replacement tires and provide service to ensure that the subject tires are replaced as promptly as possible. If a YOHTA replacement tire cannot be made available at the YOHTA tire dealer in a timely manner, another brand of tire of comparable quality and price will be used as the replacement tire. If, your dealer is unable to remedy this condition within three (3) days, we recommend you contact YOHTA's RECALL COORDINATOR for service by calling toll free: 844-921-2778 or emailing at [RECALL@YOKOHAMA-OHT.COM](mailto:RECALL@YOKOHAMA-OHT.COM)

If you no longer own this tire, please forward to YOHTA the information of the new owner. Please contact YOHTA's RECALL COORDINATOR by calling toll free: 844-921-2778 or emailing at [RECALL@YOKOHAMA-OHT.COM](mailto:RECALL@YOKOHAMA-OHT.COM)

If you have further questions or concerns, contact YOHTA’s RECALL COORDINATOR by calling toll free: 844-921-2778 or emailing at [RECALL@YOKOHAMA-OHT.COM](mailto:RECALL@YOKOHAMA-OHT.COM) or visit our website at <https://yokohama-oht.com/recalls/>

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.


If after having attempted to take advantage of this recall, you believe you have not been able to have your tire remedied without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C., 20590; or call the toll-free Vehicle Safety Hotline at 1-888- 327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We apologize for any inconvenience this safety recall may cause, but your safety is our first concern.

**SIDEWALL DRAWINGS**


A tire will be subject to this recall if it has the same five identifying characteristics marked on its sidewall that match the five characteristics of one of the tires in the chart above. The diagrams below illustrate the location of the various tire characteristics on the sidewall of each tire.

Brand	Size	Model Name	Load Range	Manufacturing Date Code	Product No.
ALLIANCE	12.5L-15FI	High Speed Rib	Load Range F	5219	54300104




Tire Sidewall Drawings of Subject Tires – Recall No. 22T 020 Continued

Brand	Size	Model Name	Load Range	Manufacturing Date Code	Product No.
ALLIANCE	11L-15F1	High Speed Rib	Load Range F	0820 or 2020	54300010




Brand	Size	Model Name	Load Range	Manufacturing Date Code	Product No.
PRIMEX	11-22.5	Highway R-550	Load Range G	0120,0520 or 2020	407366



**Tire Sidewall Drawings of Subject Tires – Recall No. 22T 020 Continued**

Brand	Size	Model Name	Load Range	Manufacturing Date Code	Product No.
ALLIANCE	11L-15FI	319	Load Range F	2020	31900030



Brand	Size	Model Name	Ply Rating	Manufacturing Date Code	Product No.
ALLIANCE	10.5-20IMP	317	12PR NYLON	2021	31706505

